

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18170-73-2970 State Number 24757

	:	EQUIPMENT INSPECTED			
State Number: 24757	Type of Unit: 1	Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 2500 Manuf: OTIS			Speed: 125	Speed: 125	
Landings: 2 Installed		3/2007	Rope Size: 0		
Volts: 208	Complied: 07/2	Complied: 07/23/2007		Entrances: 1	
OWNER		OCCUPANT			
FIDELITY BANK		FIDELITY BANK			
100 S MAIN STREET		2517 S. CHURCH STREET			
FUQUAY VARINA, NC,	27526	BURLINGTON, NC, 27215			
	IN	SPECTION INFORMATION			
Inspection Date 06/19/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
2.27.1.1.1	Place the in-car Emergency Phone in working order.				
	Repair sheetrock at bottom of walls in machine room				

Items must be corrected by: 07/19/2018 Elevator Name: FIDELITY BANK # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Sharon Oakley 3362271157 Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372 THIS IS NOT AN FIDELITY BANK

An invoice will be mailed to:

INVOICE

100 S MAIN STREET FUQUAY VARINA, NC, 27526

Page 1 of 1