



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18171-73-1267**  
State Number  
**1307**

### EQUIPMENT INSPECTED

State Number: <b>1307</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: MONARCH	Speed: 50
Landings: 2	Installed: 08/17/1949	Rope Size: 1/2
Volts: 480	Complied: 08/17/1949	Entrances: 1
OWNER	OCCUPANT	
THE TIRE CENTER OF BURLINGTON INC	THE TIRE CENTER OF BURLINGTON INC	
508 S CHURCH ST	508 S CHURCH ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

### INSPECTION INFORMATION

Inspection Date 06/20/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

### VIOLATIONS

2.11.11.5      Repair the damaged hoistway doors. Bottom

Items must be corrected by: 08/19/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Jimmy 3365163125

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

THE TIRE CENTER OF BURLINGTON INC  
508 S CHURCH ST  
BURLINGTON, NC, 27215