



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18177-73-0064
State Number
3044

EQUIPMENT INSPECTED

State Number: 3044	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 1000	Manuf: MONARCH	Speed: 75
Landings: 2	Installed: 08/25/1957	Rope Size:
Volts: 208	Complied: 08/25/1957	Entrances: 1

OWNER
FIRST CHRISTIAN CHURCH
PO BOX 1678
BURLINGTON, NC, 27215

OCCUPANT
FIRST CHRISTIAN CHURCH
415 S CHURCH ST
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 06/26/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

- 8.6.5.14.1 Provide the annual relief valve and hydraulic system pressure test. This unit is semi annually pressure tested
- 2.14.7.1.2 Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.

Items must be corrected by: 08/25/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Joan Paschal 3362267428

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

FIRST CHRISTIAN CHURCH
PO BOX 1678
BURLINGTON, NC, 27215