

THIS IS NOT AN INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18177-73-4961
State Number 2153

	Е	QUIPMENT INSPECTED		
State Number: 2153 Capacity: 4000 Landings: 3 Volts: 550 OWNER	Type of Unit: Freight Manuf: MONARCH Installed: 07/22/1953 Complied: 07/22/1953		Floor to Floor: 1 to 3 Speed: 60 Rope Size: Entrances: 2 OCCUPANT	
INTERNATIONAL TEXTILE GROUP, INC. 906 ANTHONY ST BURLINGTON, NC, 27215			BURLINGTON FINISHING 906 ANTHONY ST BURLINGTON, NC, 27215	
	INS	SPECTION INFORMATION		
Inspection Date 06/26/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
		VIOLATIONS		
Notify the Elevator Bureau in writi	ing on Corrected Violations Form v	when the following corrections	s have been made in order to bri	ng your equipment into
complainace with current codes. Violations pointed out to: Mark Johnson 3362282475		Inspector		

906 ANTHONY ST BURLINGTON, NC, 27215

INTERNATIONAL TEXTILE GROUP, INC.

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: