

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 18177-79-3448 State Number 12189

7

EQUIPMENT INSPECTED					
State Number: 12189	tate Number: 12189 Type of Unit: Pa		Floor to Floor: 1 to 2		
Capacity: 2000	Manuf: KONE		Speed: 100		
Landings: 2		Installed: 01/29/1987		Rope Size: 0 Entrances: 1	
Volts: 200	Complied: 02/0	Complied: 02/03/1987			
OWNER		OCCUPANT			
CRESCOM BANK		CRESCOM BANK			
PO BOX 2047		1311 CAROLINA AVE			
WASHINGTON, NC, 27887		WASHINGTON	N, NC, 27889		
	IN	SPECTION INFORMATION			
Inspection Date 06/26/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT	
		VIOLATIONS			
Items must be corrected by	: 08/25/2018				
otify the Elevator Bureau in womplainace with current codes	vriting on Corrected Violations Form	when the following correction	s have been made in order to bring	g your equipment into	
iolations pointed out to: main	office		Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CRESCOM BANK PO BOX 2047			

WASHINGTON, NC, 27887