



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18179-73-2233
State Number
2031

EQUIPMENT INSPECTED

State Number: 2031	Type of Unit: Passenger	Floor to Floor: 1 to 7
Capacity: 2500	Manuf: SOUTHERN	Speed: 200
Landings: 7	Installed: 09/22/1983	Rope Size: 1/2
Volts: 200	Complied: 08/25/2005	Entrances: 1

OWNER
BEACON MANAGEMENT
PO BOX 29229
GREENSBORO, NC, 27429-9229

OCCUPANT
ALAMANCE PLAZA
111 MAPLE AVE
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 06/28/2018	Type Inspection Alteration	Certificate Status Issued	Inspector 73 - James	County ALAMANCE
-------------------------------	-------------------------------	------------------------------	-------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Daniel Thyssen Krupp

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEACON MANAGEMENT
PO BOX 29229
GREENSBORO, NC, 27429-9229