NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18180-79-2133 State Number H1190

7

	F	EQUIPMENT INSPECTED		
State Number: H1190	Type of Unit:	Hand Lift	Floor to Floor: 1 to	2
Capacity: 750	Manuf: ACCESS		Speed: 10	
Landings: 2	Installed: 10/31/2001		Rope Size: 3/8	
Volts: 120	Complied: 10/31/2001		Entrances: 2	
OWNER	OCCUPANT			
BELHAVEN PUBLIC LIBRARY	Y	BELHAVEN PUBLIC LIBRARY		
333 E MAIN ST		333 E MAIN ST		
BELHAVEN, NC, 27810		BELHAVEN, N	NC, 27810	
	INS	SPECTION INFORMATION		
Inspection Date 06/29/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT
		VIOLATIONS		
Items must be corrected by: 08.		when the following correction	s have been made in order to bring	g your equipment into
complainace with current codes.	.1-		Lucusoton	
Violations pointed out to: front des			Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	BELHAVEN PUBLIC 333 E MAIN ST BELHAVEN, NC, 278		