



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18183-73-5578
State Number
20826

EQUIPMENT INSPECTED

State Number: 20826	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: SOUTHERN	Speed: 90
Landings: 2	Installed: 08/09/2002	Rope Size: 0
Volts: 208	Complied: 08/09/2002	Entrances: 1

OWNER

CAROLINA FARMERS M. INSURANCE
515A W SALISBURY ST
ASHEBORO, NC, 27203

OCCUPANT

CAROLINA FARMERS BLDG
515A W SALISBURY ST
ASHEBORO, NC, 27203

INSPECTION INFORMATION

Inspection Date 07/02/2018	Type Inspection Alteration	Certificate Status Issued	Inspector 73 - James	County RANDOLPH
-------------------------------	-------------------------------	------------------------------	-------------------------	--------------------

76

VIOLATIONS

Elevator Name: VISITOR ELEVATOR

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Aaron American Elevator

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROLINA FARMERS M. INSURANCE
515A W SALISBURY ST
ASHEBORO, NC, 27203