



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18192-65-5174
State Number
9018

EQUIPMENT INSPECTED

State Number: 9018	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 3	Installed: 11/02/1978	Rope Size: 0
Volts: 220	Complied: 11/17/1978	Entrances: 1

OWNER

AVERY COUNTY SCHOOLS
775 CRANBERRY STREET
NEWLAND, NC, 28657

OCCUPANT

AVERY COUNT MIDDLE SCHOOL
102 OLD MONTEZUMA ROAD
NEWLAND, NC, 28657

INSPECTION INFORMATION

Inspection Date 07/11/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 65 - Kelley	County AVERY
-------------------------------	----------------------------	---------------------------------	--------------------------	-----------------

6

VIOLATIONS

8.6.4.7	Clean the pit and the pit equipment.
2.7.3.4.1	Provide a self closing self-locking machine room / space door.
8.6.1.7.2	Provide the appropriate test tag.
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.
NEC	Protect machine room lighting with cage or plastic sleeves.
8.6.1.6.7	Provide / replace "Elevator Machine Room" sign on door.

Items must be corrected by: 08/10/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Michael Buchannan 828-733-6006

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AVERY COUNTY SCHOOLS
775 CRANBERRY STREET
NEWLAND, NC, 28657