



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18198-70-1159
State Number
H2265

EQUIPMENT INSPECTED

State Number: H2265	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: NATL W-O-V	Speed: 9
Landings: 2	Installed: 02/08/2011	Rope Size:
Volts: 115	Complied: 02/08/2011	Entrances: 2
OWNER	OCCUPANT	
ANSON COUNTY ARTS COUNCIL	ANSONIA THEATRE	
P.O. BOX 332	112 S RUTHERFORD STREET	
WADESBORO, NC, 28170	WADESBORO, NC, 28170	

INSPECTION INFORMATION

Inspection Date 07/17/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County ANSON
-------------------------------	----------------------------	---------------------------------	---------------------------	-----------------

4

VIOLATIONS

Elevator Name: STAGE LIFT

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Tommy Wooten 704-441-4295

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON COUNTY ARTS COUNCIL
P.O. BOX 332
WADESBORO, NC, 28170