

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18198-70-4079 State Number 14303

	E	QUIPMENT INSPECTED			
State Number: 14303 Type of Unit: Passo		enger Floor to Floor: 1 to 3			
Capacity: 2500			Speed: 125		
Landings: 3			Rope Size: Entrances: 1		
Volts: 230 Complied: 02/21/1991		991			
OWNER		OCCUPANT			
FIRST UNITED METHODIST CHURCH		FIRST UNITED METH	FIRST UNITED METHODIST CHURCH		
118 E MORGAN ST		118 E MORGAN ST	118 E MORGAN ST		
WADESBORO, NC, 28170		WADESBORO, NC, 28170			
	INS	PECTION INFORMATION			
Inspection Date 07/17/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County ANSON	
		VIOLATIONS			
Elevator Name: PASSEN	GER ELEV				
Notify the Elevator Bureau in complainace with current code	writing on Corrected Violations Form wes.	then the following corrections have be	een made in order to bring you	r equipment into	
violations pointed out to: Bet			Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	FIRST UNITED METHODIST CHURCH An invoice will be mailed to: 118 E MORGAN ST WADESBORO, NC, 28170				