

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 18198-73-4791 State Number 19632

	E	QUIPMENT INSPECTED		
State Number: 19632 Type of Unit: Pas		senger Floor to Fl		1 to 2
Capacity: 4500	71		Speed: 140	
Landings: 2			Rope Size:	
Volts: 460 Complied: 04/11/2001		2001	Entrances: 1	
OWNER		OCCUPANT	Γ	
ALAMANCE EXTENDED	CARE INC	EDGEWOOD PLACE		
1860 BROOKWOOD AVEN	NUE	1820 BROOKWOOD AVENUE		
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215		
	INS	SPECTION INFORMATION		
Inspection Date 07/17/2018	Type Inspection Alteration	Certificate Status Issued	Inspector 73 - James	County ALAMANCE
·		VIOLATIONS		
Notify the Elevator Bureau in complainace with current code	writing on Corrected Violations Form v s.	when the following corrections have	ve been made in order to br	ing your equipment int
Violations pointed out to: Jain	ne Thyssen Krupp Elevator		Inspector	
To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	ALAMANCE EXTENDED CARE INC An invoice will be mailed to: 1860 BROOKWOOD AVENUE			

1860 BROOKWOOD AVENUE BURLINGTON, NC, 27215

An invoice will be mailed to: