



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18200-65-368**  
State Number  
**22268**

EQUIPMENT INSPECTED

State Number: <b>22268</b>	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: KONE	Speed: 100
Landings: 3	Installed: 03/16/2004	Rope Size: 0
Volts: 208	Complied: 03/16/2004	Entrances: 1
OWNER	OCCUPANT	
NORTHWESTERN REGIONAL HOUSING	ELK PARK APARTMENTS	
P.O. BOX 2510	256 ELK PARK SCHOOL ROAD	
BOONE, NC, 28607	ELK PARK, NC, 28622	

INSPECTION INFORMATION

Inspection Date 07/19/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 65 - Kelley	County AVERY
-------------------------------	----------------------------	---------------------------------	--------------------------	-----------------

6

VIOLATIONS

- 2.14.7.1.3 Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) measured at any point between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o
- 8.6.4.7 Clean the hoistway and hoistway equipment.
- 2.27.1.1.1 Place the in-car Emergency Phone in working order. Operator shall verify location. (ADA)

Items must be corrected by: 09/17/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Woody Young 828-260-6949

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NORTHWESTERN REGIONAL HOUSING  
P.O. BOX 2510  
BOONE, NC, 28607