



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18214-48-3537**  
State Number  
**30974**

EQUIPMENT INSPECTED

State Number: <b>30974</b>	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 3500	Manuf: TKE	Speed: 35
Landings: 3	Installed: 09/20/2017	Rope Size:
Volts: 230	Complied:	Entrances: 1
OWNER	OCCUPANT	
HAWTHORNE RESIDENTIAL PROPERTIES	HAWTHORNE AY LELAND CAR 5	
2918A MARTINSVILLE ROAD	9490 PLOOF ROAD SE	
LELAND, NC, 27408	LELAND, NC, 28541	

INSPECTION INFORMATION

Inspection Date 08/02/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

HAWTHORNE RESIDENTIAL PROPERTIES  
2918A MARTINSVILLE ROAD  
LELAND, NC, 27408