



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18221-79-0329
State Number
6917

EQUIPMENT INSPECTED

State Number: 6917	Type of Unit: Dumbwaiter	Floor to Floor: 1 to 2
Capacity: 300	Manuf: MATOT	Speed: 50
Landings: 2	Installed: 01/28/1971	Rope Size: 1/4
Volts: 270	Complied: 01/28/1971	Entrances: 1

OWNER

BEAUFORT COUNTY COMM COLLEGE
5337 US HWY 264 EAST
WASHINGTON, NC, 27889

OCCUPANT

BEAUFORT CO COMMUNITY COLLEGE
5337 HWY 264 EAST
WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date 08/09/2018	Type Inspection Removed	Certificate Status Not Issued	Inspector 79 - Cumberland	County BEAUFORT
-------------------------------	----------------------------	----------------------------------	------------------------------	--------------------

7

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: customer no longer using unit. locked off by state.

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT COUNTY COMM COLLEGE
5337 US HWY 264 EAST
WASHINGTON, NC, 27889