

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18225-76-1099 State Number 26921

	EQ	UIPMENT INSPECTED		
State Number: 26921	Type of Unit: Pas	senger	Floor to Floor: 1 to 3	
Capacity: 2100 Manuf: Tk		8	Speed: 100	
Landings: 3	Installed: 05/14/2	009	Rope Size:	
Volts: 208		Complied: 05/14/2009		
OWNER	•	OCCUPANT		
COUNTY OF ASHE		ASHE COUNTY PUBLIC LIBRA	ARY	
150 GOVERNMENT CIRCL	(. F .	148 LIBRARY DRIVE		
JEFFERSON, NC, 28694	32	WEST JEFFERSON, NC, 28694		
	INSP	ECTION INFORMATION		
Inspection Date 08/13/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
		VIOLATIONS		
5.1.21.1 Place the car alarm	bell in working order. Minimum level of	f 80 dBA. With power off		
2.14.7.1.3 Place the in-car embetween 48 in. and	nergency lights in working order. The aux 35 in. above the car floor and approxima	tillary lighting illumination shall not lately 12 in. centered horizontally in fr	be less than 2 lx (0.2 fc) measure ont o	ed at any point
2.29.1 SECOND NOTICE ROOM	E Assign identification numbers or letters	to the equipment where required. El	evator control room needs to be	labeled, ELEVATOR
	E Articles or materials not necessary for t ntrol spaces and control rooms.	he mainternace or operation of the el	evator shall not be stored in mac	chinery spaces,
Items must be corrected by	7: 10/12/2018			
Notify the Elevator Bureau in complainace with current code	writing on Corrected Violations Form whs.	en the following corrections have be-	en made in order to bring your e	equipment into
Violations pointed out to: Sus			Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	COUNTY OF ASHE 150 GOVERNMENT CIRCLE JEFFERSON, NC, 28694		