



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18225-76-341
State Number
23882

EQUIPMENT INSPECTED

State Number: 23882	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: CEMCO	Speed: 90
Landings: 2	Installed: 12/15/2006	Rope Size: 0
Volts: 240	Complied:	Entrances: 1
OWNER W JEFFERSON UNITED METHODIST CHURCH 107 W 2ND STREET WEST JEFFERSON, NC, 28694		OCCUPANT W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET WEST JEFFERSON, NC, 28694

INSPECTION INFORMATION

Inspection Date 08/13/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------

5

VIOLATIONS

2.7.9.1	Place the machine room or space lights in working order. Flourscent tubes need to be protected
2.7.3.4.1	Provide a self closing self-locking machine room / space door.
8.6.4.13.1 (f)	Properly maintain the hoistway door rollers. (replace or adjust) top and bottom door
2.27.1.1.1	SECOND NOTICE Place the in-car Emergency Phone in working order.

Items must be corrected by: 09/02/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Karen Herzog 336-246-5292

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

W JEFFERSON UNITED METHODIST CHURCH
107 W 2ND STREET
WEST JEFFERSON, NC, 28694