



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18234-76-1986
State Number
17535

EQUIPMENT INSPECTED

State Number: 17535	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 06/08/1999	Rope Size:
Volts: 480	Complied: 06/08/1999	Entrances: 1
OWNER		OCCUPANT
ASHE COUNTY BOARD OF EDUCATION		ASHE COUNTY HIGH SCHOOL
PO BOX 604		184 CAMPUS DR
JEFFERSON, NC, 28640		WEST JEFFERSON, NC, 28694

INSPECTION INFORMATION

Inspection Date 08/22/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------

5

VIOLATIONS

- 2.14.7.1.3 Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) measured at any point between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o
- 5.1.21.1 Place the car alarm bell in working order. Minimum level of 80 dBA. With power off

Items must be corrected by: 09/21/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Kenny 336-246-7175

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ASHE COUNTY BOARD OF EDUCATION
PO BOX 604
JEFFERSON, NC, 28640