



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18234-76-3965
State Number
27737

EQUIPMENT INSPECTED

State Number: 27737	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: TKE	Speed: 100
Landings: 3	Installed: 09/07/2011	Rope Size:
Volts: 208	Complied: 09/07/2011	Entrances: 2

OWNER

MIDWAY BAPTIST CHURCH
1670 MT JEFFERSON ROAD
WEST JEFFERSON, NC, 28694

OCCUPANT

MIDWAY BAPTIST CHURCH
1670 MT JEFFERSON ROAD
WEST JEFFERSON, NC, 28640

INSPECTION INFORMATION

Inspection Date 08/22/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------

5

VIOLATIONS

8.6.5.14.1 SECOND NOTICE Provide the annual relief valve and hydraulic system pressure test.

Items must be corrected by: 09/21/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Pastor 336-246-2012

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MIDWAY BAPTIST CHURCH
1670 MT JEFFERSON ROAD
WEST JEFFERSON, NC, 28694