

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 18248-73-4090 State Number 8437

	Е	QUIPMENT INSPECTED		
State Number: 8437 Type of Unit: F		ght Floor to Floor: 1 to 3		
Capacity: 10000 Manuf: SOUTHERN		Speed: 60		
Landings: 3 Installed: 07/25/1988		Rope Size:		
Volts: 480 Complied: 04/25		/1989	Entrances: 1	
OWNER		OCCUPANT		
NOVA FLEX HOSE CO		NOVA FLEX HOSE CO		
449 /TROLLINGWOOD ROAD 449 TROLLINGWOOD ROAD				
HAW RIVER, NC, 27258		HAW RIVER, NC, 27258		
	INS	PECTION INFORMATION		
Inspection Date 09/05/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
		VIOLATIONS		
	writing on Corrected Violations Form w	hen the following corrections ha	ve been made in order to br	ing your equipment into
omplainace with current code			•	
iolations pointed out to: Ker	1 Jones 3363951210		Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	NOVA FLEX HOSE CO 449 /TROLLINGWOOD R	ROAD	

An invoice will be mailed to:

449 /TROLLINGWOOD ROAD HAW RIVER, NC, 27258