

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18248-73-5292 State Number 23101

	<u>.</u>	EQUIPMENT INSPECTED			
State Number: 23101 Type of Unit: Pa		Passenger	ssenger Floor to Floor: 1 to 4		
Capacity: 2500 Manuf: OTIS			Speed: 125		
Landings: 4 Installed: 12/28/2005		8/2005	Rope Size: .		
Volts: 208			Entrances: 1		
OWNER		OCCUPANT			
FIRST REFORMED UNITED CHURCH		FIRST REFORMED UNITED CHURCH			
513 W FRONT ST		513 W FRONT ST			
BURLINGTON, NC, 27215		BURLINGTON, NC	BURLINGTON, NC, 27215		
	IN:	SPECTION INFORMATION			
Inspection Date 09/05/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
8.6.4.7 Remove the water	from the pit floor and take steps to	prevent its re-entry.			
Items must be corrected by: 1	1/04/2018				
Notify the Elevator Bureau in wri	1/04/2018 ting on Corrected Violations Form	when the following corrections hav	e been made in order to br	ing your equipment into	
Notify the Elevator Bureau in wri omplainace with current codes.	ting on Corrected Violations Form	when the following corrections hav	Inspector	ing your equipment into	
•	ting on Corrected Violations Form	-	Inspector		