

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18254-70-1335 State Number 25634

		EQUIPMENT INSPECTED			
State Number: 25634 Type of Unit:		t: Freight	eight Floor to Floor: 1 to 2		
Capacity: 20000	Manuf: OT	IS	Speed: 50		
Landings: 2 Installed: 12/2.		2/22/2008	Rope Size:	Size:	
Volts: 480	Complied:		Entrances: 1		
OWNER POST CONSUMER BRANDS		OCCUPANT			
		POST CONSUM	ER BRANDS		
2525 BANK STREET		2525 BANK STR	REET		
ASHBORO, NC, 27203		ASHBORO, NC, 27203			
		NSPECTION INFORMATION			
Inspection Date 09/11/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County RANDOLPH	
		VIOLATIONS			
2.27.1.1.1 Place the in-car Eme8.6 Provide monthly fire8.6 provide oil log					
Items must be corrected by: Notify the Elevator Bureau in wr complainace with current codes. Violations pointed out to: Al Sp	riting on Corrected Violations Form			oring your equipment into	
violations pointed out to: Al Sp					
THIS IS NOT AN INVOICE	To make changes to the invoice n An invoice will be mailed to:	pailing address please call: 919-7 POST CONSUMER BR. 2525 BANK STREET ASHBORO, NC 27203			