



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18260-70-1450**  
State Number  
**1167**

EQUIPMENT INSPECTED

State Number: <b>1167</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 75
Landings: 2	Installed: 10/11/1948	Rope Size: 1/2
Volts: 220	Complied: 10/11/1948	Entrances: 1
OWNER	OCCUPANT	
RANDOLPH CO SENIOR ADULTS ASSOC,INC	RANDOLPH CO SR ADULTS ASSOC,INC	
PO BOX 1852	347 WEST SALISBURY ST	
ASHEBORO, NC, 28204-1852	ASHEBORO, NC, 27203	

INSPECTION INFORMATION

Inspection Date 09/17/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

76

VIOLATIONS

8.6.4.7	Remove the water from the pit floor and take steps to prevent its re-entry.
8.6.4.19.2 (b)	Provide the annual no load test.

Items must be corrected by: 11/16/2018

Elevator Name: Plant 3

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Steve McGlohon 336-629-7433

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

RANDOLPH CO SENIOR ADULTS ASSOC,INC  
PO BOX 1852  
ASHEBORO, NC, 28204-1852