



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18261-70-2545**  
State Number  
**9443**

EQUIPMENT INSPECTED

State Number: <b>9443</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 3500	Manuf: SOUTHERN	Speed: 75
Landings: 2	Installed: 06/13/1979	Rope Size:
Volts: 220	Complied: 06/13/1979	Entrances: 1
OWNER	OCCUPANT	
ACME MCCRARY CORP	ACME MCCRARY CORP	
BOX 1287	159 NORTH STREET	
ASHEBORO, NC, 27204-1287	ASHEBORO, NC, 27203	

INSPECTION INFORMATION

Inspection Date 09/18/2018	Type Inspection Routine	Certificate Status Not Issued	Inspector 70 - Darnley	County RANDOLPH
-------------------------------	----------------------------	----------------------------------	---------------------------	--------------------

76

VIOLATIONS

8.6.5.7	Provide an oil usage log in the machine room.
2.2.5.1	Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.
2.2.5.1	Place the freight cab interior lights in working order. 25 lx or 2.5 fc @ the cab floor.
8.6.4.7	Remove the water from the pit floor and take steps to prevent its re-entry.
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.

Items must be corrected by: 11/17/2018

Elevator Name: Shipping

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Grey Plummer 336-625-2161

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ACME MCCRARY CORP  
BOX 1287  
ASHEBORO, NC, 27204-1287