



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18263-70-1416
State Number
6280

EQUIPMENT INSPECTED

State Number: 6280	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 6000	Manuf: SOUTHERN	Speed: 75
Landings: 2	Installed: 01/09/1969	Rope Size:
Volts: 550	Complied: 12/29/1997	Entrances: 1
OWNER	OCCUPANT	
SAPONA MFG COMPANY	SAPONA MANUFACTURING CO	
PO BOX 128	2478 CEDAR FALLS RD	
CEDAR FALLS, NC, 27230	CEDAR FALLS, NC, 27230	

INSPECTION INFORMATION

Inspection Date 09/20/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

76

VIOLATIONS

8.6.1.6.2 Empty the drip pan in the machine room.

Items must be corrected by: 11/19/2018

Elevator Name: MIDDLE ELEVATOR #3

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Ken Grant 336-625-2727

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SAPONA MFG COMPANY
PO BOX 128
CEDAR FALLS, NC, 27230