

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18289-76-3930 State Number 26921

	EÇ	QUIPMENT INSPECTED			
State Number: 26921	Type of Unit: Pa	ssenger	Floor to Floor: 1 to 3		
Capacity: 2100	Manuf: TKE		Speed: 100		
Landings: 3 Installed: 05/14/2009 Volts: 208 Complied: 05/14/2009		2009	Rope Size: Entrances: 2		
		/2009			
OWNER	-	OCCUPANT			
	COUNTY OF ASHE ASHE COUNTY PUBLIC LIBRARY 150 GOVERNMENT CIRCLE 148 LIBRARY DRIVE				
JEFFERSON, NC, 28694	EFFERSON, NC, 28694 WEST JEFFERSON, NC, 28694				
	INSI	PECTION INFORMATION			
Inspection Date 10/16/2018	Type Inspection Compliance	Certificate Status Prev Issued	Inspector 76 - Crank	County ASHE	
		VIOLATIONS			
	writing on Corrected Violations Form when	hen the following corrections have bee	en made in order to bring your e	quipment into	
complainace with current code Violations pointed out to: Sus			Inspector		
		ing address please call: 010 733 0372			
THIS IS NOT AN	To make changes to the invoice mailing address please call: 919-733-0372 COUNTY OF ASHE				
INVOICE	An invoice will be mailed to:	150 GOVERNMENT CIRCLE JEFFERSON, NC, 28694			