



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18298-70-0777
State Number
9457

EQUIPMENT INSPECTED

State Number: 9457	Type of Unit: Passenger	Floor to Floor: 1 to 6
Capacity: 2000	Manuf: THYSSEN KRUPP	Speed: 150
Landings: 6	Installed: 06/13/1980	Rope Size:
Volts: 220	Complied: 02/07/1997	Entrances: 1
OWNER	OCCUPANT	
ASHEBORO SUMMIT	ASHEBORO SUMMIT	
156 EAST ACADEMY ST	156 EAST ACADEMY ST BOX 6	
ASHEBORO, NC, 27203	ASHEBORO, NC, 27203	

INSPECTION INFORMATION

Inspection Date 10/25/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

76

VIOLATIONS

Manager

Elevator Name: #1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Manager 336-625-6800

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ASHEBORO SUMMIT
156 EAST ACADEMY ST
ASHEBORO, NC, 27203