



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18310-57-4318**  
State Number  
**29883**

EQUIPMENT INSPECTED

State Number: <b>29883</b>	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 3500	Manuf: CANTON	Speed: 123
Landings: 4	Installed: 12/30/2015	Rope Size:
Volts: 208	Complied: 12/30/2015	Entrances: 1
OWNER	OCCUPANT	
WHITE FURNITURE COMPANY	WHITE FURNITURE COMPANY CAR 1	
201 S CENTER STREET	201 S CENTER STREET	
MEBANE, NC, 27302	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 11/06/2018	Type Inspection Routine	Certificate Status Not Issued	Inspector 57 - Evans	County ALAMANCE
-------------------------------	----------------------------	----------------------------------	-------------------------	--------------------

1

VIOLATIONS

- 8.6.5.5.1 Where pressure piping, valves, and cylinders use packing glands or seals, they shall be examined and maintained to prevent excessive loss of fluid.  
(Replace packing. - ELEVATOR NOT TO BE USED UNTIL COMPLETED AND INSPECTED BY NCDOL)
- 8.6.4.8 Clean the oil from the machine room floor and pit.
- 8.6.5.7 Provide an oil usage log in the machine room.
- 8.6 Scavenger line not to be run through wall, but to a bucket in the pit.

Items must be corrected by: 01/05/2019

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into  
complainance with current codes.

Violations pointed out to: LINDA LOCKLEAR (919)717-0400

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

WHITE FURNITURE COMPANY  
201 S CENTER STREET  
MEBANE, NC, 27302