



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
19079-70-0425
State Number
25634

EQUIPMENT INSPECTED

State Number: 25634	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 20000	Manuf: OTIS	Speed: 50
Landings: 2	Installed: 12/22/2008	Rope Size:
Volts: 480	Complied:	Entrances: 1
OWNER	OCCUPANT	
POST CONSUMER BRANDS	POST CONSUMER BRANDS	
2525 BANK STREET	2525 BANK STREET	
ASHBORO, NC, 27203	ASHBORO, NC, 27203	

INSPECTION INFORMATION

Inspection Date 03/20/2019	Type Inspection Compliance	Certificate Status Prev Issued	Inspector 70 - Darnley	County RANDOLPH
-------------------------------	-------------------------------	-----------------------------------	---------------------------	--------------------

76

VIOLATIONS

2.27.1.1.1 Place the in-car Emergency Phone in working order.

Items must be corrected by: 04/19/2019

Elevator Name: RTE BLDG LINE 1 & 2

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Al Spencer and Terrence Franklin 336-683-5507

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

POST CONSUMER BRANDS
2525 BANK STREET
ASHBORO, NC, 27203