



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
19136-76-3154
State Number
20971

EQUIPMENT INSPECTED

State Number: 20971	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 95
Landings: 2	Installed: 05/15/2002	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
LIFE STORE BANK	LIFE STORE BANK	
1441 MT. JEFFERSON RD	1441 MT. JEFFERSON	
W. JEFFERSON, NC, 28694	W. JEFFERSON, NC, 28694	

INSPECTION INFORMATION

Inspection Date 05/16/2019	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------

5

VIOLATIONS

8.6.5.14.1 Provide the annual relief valve and hydraulic system pressure test.

Items must be corrected by: 07/15/2019

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Amy 336-246-4344

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LIFE STORE BANK
1441 MT. JEFFERSON RD
W. JEFFERSON, NC, 28694