



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
19295-78-3010
State Number
10065

EQUIPMENT INSPECTED

State Number: **10065** Type of Unit: Passenger Floor to Floor: M to 14
Capacity: 3500 Manuf: WESTINGHOUSE Speed: 450
Landings: 13 Installed: 03/05/1982 Rope Size: 5/8
Volts: 480 Complied: 04/29/1982 Entrances: 1

OWNER
SOUTH COLLEGE STREET LLC
201 S COLLEGE ST SUITE 2270
CHARLOTTE, NC, 28244

OCCUPANT
CHARLOTTE PLAZA
201 S. COLLEGE ST.
CHARLOTTE, NC, 28244

INSPECTION INFORMATION

| Inspection Date | Type Inspection | Certificate Status | Inspector | County | |
|-----------------|-----------------|--------------------|--------------|-------------|------|
| 10/22/2019 | Routine | Re-issued | 78 - Cardona | MECKLENBURG | 60 G |

VIOLATIONS

- 8.6.4.1.1 Suspension ropes shall be kept clean and lightly lubricated.
- 8.6.11.1 Provide a monthly log on the results of the Phase I and Phase II operations.
- NCR Recommend taking steps to minimize "construction debri / dust" blown into machine room. (Noticed excessive "dust" blown on elevator controllers, machines, sspension means, etc
- 8.6.1.4 Maintenance records shall document compliance with Section 8.6. Instructions for locating the maintenance records of each unit for viewing on-site, shall be posted on the controller or at the means necessary for test

Items must be corrected by: 12/21/2019

Elevator Name: ELEVATOR #2

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainance with current codes.

Violations pointed out to: Haydon Moffat 704 661 5715

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SOUTH COLLEGE STREET LLC
201 S COLLEGE ST SUITE 2270
CHARLOTTE, NC, 28244