



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
22244-102-3360
State Number
10065

EQUIPMENT INSPECTED

State Number: **10065** Type of Unit: Passenger Floor to Floor: M to 14
Capacity: 3500 Manuf: WESTINGHOUSE Speed: 450
Landings: 13 Installed: 03/05/1982 Rope Size: 5/8
Volts: 480 Complied: 04/29/1982 Entrances: 1

OWNER
SOUTH COLLEGE STREET LLC
201 S COLLEGE ST SUITE 2270
CHARLOTTE, NC, 28244

OCCUPANT
CHARLOTTE PLAZA
201 S. COLLEGE ST.
CHARLOTTE, NC, 28244

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County	
09/01/2022	Routine	Re-issued	102 - Mchugh	MECKLENBURG	60 G

VIOLATIONS

- 8.6.4.7 Clean the pit and the pit equipment.
- 2.27.9 MISSING SIGNS IN CASE OF FIRE DON' T USE ELEVATORS TAKE STAIRS M,5,6,7,8,10 AND 14 VERBAGE ON 12 IS INCORRECT
- 8.6 WORM SEAL LEAKING NEEDS TO BE RE PACKED
- 8.6 ROPES GETTING LOW IN SHEAVE MIGHT NEED TO BE REGROOVED

Items must be corrected by: 10/31/2022

Elevator Name: ELEVATOR #2

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainance with current codes.

Violations pointed out to: LARRY 704-900-9792

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SOUTH COLLEGE STREET LLC
201 S COLLEGE ST SUITE 2270
CHARLOTTE, NC, 28244