



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
25104-102-1459
State Number
10065

EQUIPMENT INSPECTED

State Number: **10065** Type of Unit: Passenger Floor to Floor: M to 14
Capacity: 3500 Manuf: WESTINGHOUSE Speed: 450
Landings: 13 Installed: 03/05/1982 Rope Size: 5/8
Volts: 480 Complied: 04/29/1982 Entrances: 1

OWNER
SOUTH COLLEGE STREET LLC
201 S COLLEGE ST SUITE 2270
CHARLOTTE, NC, 28244

OCCUPANT
CHARLOTTE PLAZA
201 S. COLLEGE ST.
CHARLOTTE, NC, 28244

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County	
04/14/2025	Routine	Re-issued	102 - Mchugh	MECKLENBURG	60 D

VIOLATIONS

- 2.24.8.6 Seal the drive machine oil leaks.WORM LEAKING NEEDS NEW PACKING
- 8.6 REMOVE PAINT FROM TOP FLOOR ACCESS SWITCH
- 2.24.8.6 Seal the drive machine oil leaks.WORM LEAKING NEEDS NEW PACKING
- 8.6 REMOVE PAINT FROM TOP FLOOR ACCESS SWITCH

Items must be corrected by: 06/13/2025

Elevator Name: ELEVATOR #2

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainance with current codes.

Violations pointed out to: larry.stinar@foundrycommercial.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SOUTH COLLEGE STREET LLC
201 S COLLEGE ST SUITE 2270
CHARLOTTE, NC, 28244