NCDOL NCDOL

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9110-36-137
State Number 26329

1

	E	QUIPMENT INSPECTED			
State Number: 26329	Type of Unit: Passenger		Floor to Floor: 1 to 2		
Capacity: 2100	Manuf: TKE		Speed: 80		
Landings: 2	Installed: 04/20/2009		Rope Size: 0		
Volts: 460	Complied: 04/20/2009		Entrances: 1		
OWNER		OCCUPANT			
THYSSEN KRUPP	ELON UNIVERSITY LINDER BLDG				
103 EAST JJ DRIVE	603 W HAGGARD AVENUE				
GREENSBORO NC, NC, 27406		ELON, NC, 27244			
	INS	SPECTION INFORMATION			
Inspection Date 04/20/2009	Type Inspection New	Certificate Status Issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
Elevator Name: LINDER BLI	OG				
	ng on Corrected Violations Form v	when the following corrections l	have been made in order to bri	ng your equipment into	
Violations pointed out to: DWIGHT COBLE			Inspector		
	Fo make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN	An invoice will be mailed to:	THYSSEN KRUPP 103 EAST JJ DRIVE GREENSBORO NC, NC			