



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**9121-24-025**  
State Number  
**22267**

### EQUIPMENT INSPECTED

State Number: <b>22267</b>	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 2100	Manuf: VERTX	Speed: 90
Landings: 7	Installed: 03/22/2005	Rope Size:
Volts: 208	Complied: 05/02/2005	Entrances: 2
OWNER		OCCUPANT
37 HIAWASSEE CONDOMINIUM ASSOC. INC.		37 HIAWASSEE CONDOMINIUM ASSOC.INC.
37 HIAWASSEE STREET		37 HIAWASSEE STREET
ASHEVILLE, NC, 28801		ASHEVILLE, NC, 28801

### INSPECTION INFORMATION

Inspection Date 05/01/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 24 - Moore	County BUNCOMBE	11 B
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------	------

### VIOLATIONS

2.7.5.2 Put the machine room ventilation in proper working order. Power to disconnect and fuse was O.K.. Couldnot hear and fan or feel any air movement.  
Room too hot.

Items must be corrected by: 05/31/2009

Elevator Name: ELEVATOR # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into  
complainace with current codes.

Violations pointed out to: Left in Office

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

37 HIAWASSEE CONDOMINIUM ASSOC. INC.  
37 HIAWASSEE STREET  
ASHEVILLE, NC, 28801