



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
9133-36-0951
State Number
H1544

EQUIPMENT INSPECTED

State Number: **H1544**

Capacity: 550

Landings: 4

Volts: 220

Type of Unit: Hand Lift

Manuf: GARAVENTA

Installed: 10/11/2004

Complied: 10/11/2004

Floor to Floor: 1 to 4

Speed: 20

Rope Size:

Entrances: 2

OWNER

ALAMANCE BURLINGTON SCHOOL
1712 VAUGHN ROAD
BURLINGTON, NC, 27217

OCCUPANT

GROVE PARK ELEMENTARY
141 TRAIL ONE
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date
05/13/2009

Type Inspection
Routine

Certificate Status
Re-issued

Inspector
36 - Kirkman

County
ALAMANCE

1

VIOLATIONS

No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE BURLINGTON SCHOOL
1712 VAUGHN ROAD
BURLINGTON, NC, 27217