



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
9139-48-0942
State Number
20869

EQUIPMENT INSPECTED

| | | |
|----------------------------|-------------------------|------------------------|
| State Number: 20869 | Type of Unit: Passenger | Floor to Floor: 1 to 4 |
| Capacity: 2500 | Manuf: OTIS | Speed: 100 |
| Landings: 4 | Installed: 02/04/2003 | Rope Size: 0 |
| Volts: 208 | Complied: 02/04/2003 | Entrances: 1 |

OWNER

1769 HORBORAGE CONDO
1769 HORBORAGE DR.
OCEAN ISLE, NC, 28469

OCCUPANT

1769 HORBORAGE CONDO
1769 HORBORAGE DRIVE
OCEAN ISLE, NC, 28469

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|--------------------------|---------------------|
| Inspection Date 05/19/2009 | Type Inspection Routine | Certificate Status Re-issued | Inspector 48 - Martin | County BRUNSWICK |
|-------------------------------|----------------------------|---------------------------------|--------------------------|---------------------|

10

VIOLATIONS

2.7.2.1 Elevator equipment only to be located in the machine room. REMOVE AL NON ELEV. EQUIPMENT.

Items must be corrected by: 06/08/2009

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

1769 HORBORAGE CONDO
1769 HORBORAGE DR.
OCEAN ISLE, NC, 28469