

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9166-36-5689
State Number 13815

1

			EQUIPMENT INSPECTED		
State Number: 13815		Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 2100		Manuf: THYSSEN KRUPP		Speed: 125	
Landings: 2		Installed: 10/25/1990		Rope Size:	
Volts: 208		Complied: 10/25/1990		Entrances: 1	
OWNER		OCCUPANT			
ALAMANCE CO SCHOOLS		GRAHAM MIDDLE SCHOOL			
1712 VAUGHAN RD		311 PINE STREET			
BURLINGTON, NC, 27217		GRAHAM, NC, 27253			
		I	NSPECTION INFORMATION		
Inspection Date 06/15/2009		Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
			VIOLATIONS		
2.11.3.1	Put the car door	r door closure device in proper working order. (Door Slamming)			
2.14.7.1.3	Put the in car en	the in car emergency light in working order.			
2.14.7.1.4 Put the car top light in working order.					

Items must be corrected by: 07/15/2009

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: office Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

An invoice will be mailed to: 1712

ALAMANCE CO SCHOOLS 1712 VAUGHAN RD BURLINGTON, NC, 27217