

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9166-48-3314
State Number 15135

	E	QUIPMENT INSPECTED			
State Number: 15135 Type of Unit: Pass		=	Floor to Floor: 1 to 2		
Capacity: 2500	Manuf: THYSSEN KRUPP		Speed: 100		
Landings: 2 Volts: 480	Installed: 01/06/1994 Complied: 01/06/1994		Rope Size: Entrances: 1		
	•		Entrances. 1		
OWNER	HED CLUD	OCCUPANT	EOD EL DEDLA		
			TREE APTS FOR ELDERLY WY 701 BUSINESS		
RALEIGH, NC, 27619			CLARKTON, NC, 28433		
		CLARKTON, NC,			
	INS	PECTION INFORMATION			
Inspection Date 06/15/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN	
		VIOLATIONS			
n/a No viola	tions found				
Notify the Elevator Bureau in was omplainace with current codes.		when the following corrections have be	een made in order to bring yo	our equipment into	
Violations pointed out to: UNA			Inspector		
	To make changes to the invoice ma	iling address please call: 919-733-037			
THIS IS NOT AN	ELM TREE LIMITED PARTNERSHIP				
INVOICE	An invoice will be mailed to:	invoice will be mailed to: P O BOX 18447 RALEIGH, NC, 27619			