



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
9173-8-5861
State Number
H2079

EQUIPMENT INSPECTED

State Number: H2079	Type of Unit: Hand Lift	Floor to Floor: 1 to 1
Capacity: 750	Manuf: SAVARIA	Speed: 8
Landings: 2	Installed: 03/04/2009	Rope Size:
Volts: 120	Complied: 03/04/2009	Entrances: 2

OWNER

ANSON COUNTY GOVERNMENT
101 S GREENE STREET
WADESBORO, NC, 28170

OCCUPANT

ANSON COUNTY ADMIN OFB
101 S GREENE STREET
WADESBORO, NC, 28170

INSPECTION INFORMATION

Inspection Date 06/22/2009	Type Inspection Compliance	Certificate Status Prev Issued	Inspector 8 - Burris	County ANSON
-------------------------------	-------------------------------	-----------------------------------	-------------------------	-----------------

4

VIOLATIONS

Elevator Name: 2ST FLOOR LIFT

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: REP- JEFF WAISNER

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON COUNTY GOVERNMENT
101 S GREENE STREET
WADESBORO, NC, 28170