

Violations pointed out to: RUSSELL TYLER

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9189-48-2810 State Number 7119

10

		EQUIPMENT INSPECTED		
State Number: 7119	Type of Unit: Passenger		Floor to Floor: 1 to 4	
Capacity: 2000	Manuf: THYSSEN KRUPP		Speed: 200	
Landings: 4	Installed: 10/24/1973		Rope Size: 1/2	
Volts: 480	Complied: 12/10/1973		Entrances: 1	
OWNER	OCCI	UPANT		
PROGRESS ENERGY	PROGRESS ENERGY - RADWASTE BLDG.			
8470 RIVER ROAD SE	8470 RIVER ROAD SE			
SOUTHPORT, NC, 28461	SOUT	SOUTHPORT, NC, 28461		
	I	INSPECTION INFORMATION		
Inspection Date 07/08/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
		VIOLATIONS		
8.6.4.1.1	Clean the hoist ropes.			
5.1.21.1	Put the in car alarm bell in working order.			
N/A	REPAIR CAR BUTTON LIGHTS			
N/A	REPAIR HALL BUTTO N LIGHTS			
Items must be corrected	by: 08/07/2009			
		1 4 6 11 1	1 1 1 1 1 1 .	1
Notity the Elevator Bureau in omplainace with current coo	n writing on Corrected Violations Forr des.	m when the following corrections	nave been made in order to	oring your equipment i

PROGRESS ENERGY

8470 RIVER ROAD SE

SOUTHPORT, NC, 28461

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ____