

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9202-7-5351
State Number H1027

5

	E0	QUIPMENT INSPECTED			
State Number: H1027 Type of Unit: Ha		Hand Lift	Floor to Floor: 1 to 2		
Capacity: 495	Manuf: GARA	Manuf: GARAVENTA			
Landings: 2	Installed: 02/01	Installed: 02/01/2000			
Volts: 220	Complied: 02/2	Complied: 02/21/2000			
OWNER		OCCUPANT			
ASHE CO SCHOOLS		ASHE CO MIDDLE SCHOOL			
PO BOX 604		255 NORTHWEST DR			
JEFFERSON, NC, 28640		WARRENSVILLE, NC, 28693			
	INS	PECTION INFORMATION			
Inspection Date 07/21/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ASHE	
		VIOLATIONS			
Notify the Elevator Bureau in complainace with current code	writing on Corrected Violations Form w	hen the following corrections have b	een made in order to bring your e	quipment into	
Violations pointed out to: ashe co. board of ed 336-246-7175			Inspector		
		ling address places call, 010 722 02			
THIS IS NOT AN	To make changes to the invoice mailing address please call: 919-733-0372		12		
INVOICE	An invoice will be mailed to:	ASHE CO SCHOOLS PO BOX 604 JEFFERSON, NC, 28640			