## NCDOL NCDOL NA Department of John

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9208-48-5290 State Number 23068

	Е	QUIPMENT INSPECTED			
State Number: 23068 Type of Unit: Passenger		assenger	Floor to Floor: 1 to 4		
Capacity: 3500	Manuf: OTIS Installed: 09/09/2005		Speed: 100	Speed: 100 Rope Size:	
Landings: 4			Rope Size:		
Volts: 240 Complied: 09/13/2005		3/2005	Entrances: 2		
OWNER		OCCUPANT			
LUCAS DEVELOPMENT		WATERWAY LANDING CONDOS			
1156 INDIGO CIRCLE	1156 INDIGO CIRCLE PARK ROAD				
SUNSET BEACH, NC, 28468		SUNSET BEACH, NC, 28	BEACH, NC, 28468		
		PECTION INFORMATION			
Inspection Date 07/27/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Items must be corrected by: 08	8/06/2009				
Notify the Elevator Bureau in write complainace with current codes.	ing on Corrected Violations Form w	when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: MANAGEMENT			Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	LUCAS DEVELOPMEN 1156 INDIGO CIRCLE SUNSET BEACH, NC, 2			