

THIS IS NOT AN INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9222-48-2175
State Number 20861

	EQUIPMENT INSPECTED			
Type of Unit: Passenger Manuf: OTIS Installed: 10/16/2002 Complied: 10/16/2002		Floor to Floor: 1 to 3 Speed: 150 Rope Size: 0 Entrances: 1		-
	OCCUPANT			
SEA TRAIL CORPORATION 279 CLUBHOUSE ROAD		SEA TRAIL CHAMPIONS #36 139 AVIAN DRIVE		
]				-
Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
	VIOLATIONS			
n car emergency telephone in pro	per working order.			
•	per working order.			
n car emergency telephone in pro	per working order. The working order is a second order in the following corrections is a second order.	have been made in order to	bring your equipment into	
	Manuf: OTIS Installed: 10 Complied: 10 Type Inspection Routine	Manuf: OTIS Installed: 10/16/2002 Complied: 10/16/2002 OCCUPANT SEA TRAIL CHAI 139 AVIAN DRIV SUNSET BEACH, INSPECTION INFORMATION Type Inspection Routine Certificate Status Re-issued VIOLATIONS	Manuf: OTIS Installed: 10/16/2002 Rope Size: 0 Complied: 10/16/2002 Entrances: 1 OCCUPANT SEA TRAIL CHAMPIONS #36 139 AVIAN DRIVE SUNSET BEACH, NC, 28468 INSPECTION INFORMATION Type Inspection Routine Certificate Status Re-issued VIOLATIONS VIOLATIONS	Manuf: OTIS Installed: 10/16/2002 Rope Size: 0 Complied: 10/16/2002 Entrances: 1 OCCUPANT SEA TRAIL CHAMPIONS #36 139 AVIAN DRIVE SUNSET BEACH, NC, 28468 INSPECTION INFORMATION Type Inspection Routine Certificate Status Re-issued VIOLATIONS VIOLATIONS

SEA TRAIL CORPORATION 279 CLUBHOUSE ROAD SUNSET BEACH, NC, 28468