



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
9237-36-0720
State Number
H1261

EQUIPMENT INSPECTED

State Number: H1261	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: GARAVENTA	Speed: 11
Landings: 2	Installed: 07/12/2002	Rope Size: .
Volts: 220	Complied: 07/12/2002	Entrances: 2
OWNER	OCCUPANT	
ALAMANCE CO SCHOOLS	ALTAMAHAW/OSSIPPEE ELEMENTARY SCHOOL	
1712 VAUGHAN RD	2832 N HWY 87	
BURLINGTON, NC, 27217	ELON, NC, 27244	

INSPECTION INFORMATION

Inspection Date 08/25/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

None found at time of inspection

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE CO SCHOOLS
1712 VAUGHAN RD
BURLINGTON, NC, 27217