

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9280-36-2846
State Number 20809

1

		EQUIPMENT INSPECTED			
State Number: 20809 Type of Unit: Pass		enger Floor to Floor: 1 to 2		1 to 2	
Capacity: 2500	Manuf: THYSSEN KRUPP		Speed: 95		
Landings: 2	Installed: 07/30/2002		Rope Size: 0		
Volts: 208	Complied: 07/30/2002		Entrances: 1		
OWNER		OCCUPANT			
ST. MARK'S REFORMED CH	URCH	ST. MARK'S REI	ST. MARK'S REFORMED CHURCH		
1230 ST. MARK'S CH. RD.		1230 ST. MARK'	S CH. RD.		
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	IN	SPECTION INFORMATION			
Inspection Date 10/07/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
None found at time of inspecti	on				
1					
otify the Elevator Bureau in wri	ting on Corrected Violations Form	when the following corrections l	have been made in order to bri	ng your equipment int	
iolations pointed out to: office			Inspector		
	To make changes to the invoice m				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ST. MARK'S REFORM 1230 ST. MARK'S CH. I BURLINGTON, NC, 272	RD.		