

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9293-36-4891
State Number 20372

1

	E	QUIPMENT INSPECTED			
State Number: 20372	Type of Unit: Pass	Type of Unit: Passenger		Floor to Floor: 1 to 3	
Capacity: 2500	Manuf: THYSSEN	Manuf: THYSSEN KRUPP		Speed: 100	
Landings: 3	Installed: 11/14/20	Installed: 11/14/2001		Rope Size:	
Volts: 208	Complied: 11/14/2001		Entrances: 3	Entrances: 3	
OWNER	OCCUPANT				
B.C. PARKER REAL ESTATE		DELANEY CROSSING BLDG #4			
336-226-8411		2229 DELANEY ST			
BURLINGTON, NC, 27408		BURLINGTON, NC, 28215			
	INS	PECTION INFORMATION			
Inspection Date 10/20/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
140 Violations found					
	ting on Corrected Violations Form v	when the following corrections l	nave been made in order to bri	ng your equipment into	
omplainace with current codes.			T		
/iolations pointed out to: office					
	To make changes to the invoice ma	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	B.C. PARKER REAL ES 336-226-8411 BURLINGTON, NC, 274			