NCD DL

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9299-36-1150
State Number 26097

1

	E	QUIPMENT INSPECTED			
State Number: 26097	Type of Unit: P	'assenger	Floor to Floor: 1	to 3	
Capacity: 2500	Manuf: SCHIN	Manuf: SCHINDLER			
Landings: 3	Installed: 05/13/2008		Rope Size:		
Volts: 208	Complied: 05/13/2008		Entrances: 1		
OWNER		OCCUPANT			
ETHAN POINTE	ETHAN POINTE APTS BLDG 3				
1176 KIRKPATRICK ROAD	1176 KIRKPATRICK RD				
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 10/26/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
Elevator Name: BUILDING a Notify the Elevator Bureau in writ complainace with current codes. Violations pointed out to: office	# 3 ing on Corrected Violations Form v	when the following corrections l			
*					
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ETHAN POINTE 1176 KIRKPATRICK RO BURLINGTON, NC, 272			