

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9316-36-0936
State Number 24169

1

| | E | EQUIPMENT INSPECTED | | | |
|--|--|----------------------------------|--------------------------------|------------------------|--|
| State Number: 24169 | Type of Unit: Passenger | | Floor to Floor: 1 to 3 | | |
| Capacity: 2500 | Manuf: THYSSEN KRUPP | | Speed: 100 | | |
| Landings: 3 | Installed: 09/20/2006 | | Rope Size: 0 | | |
| Volts: 208 | Complied: 09/20/2006 | | Entrances: 1 | | |
| OWNER | | OCCUPANT | | | |
| SHADS LANDING | CEDAR RIDGE RETIREMENT CENTER | | | | |
| 5101 PROSPERITY CHURCH | H ROAD 2680 MEBANE STREET | | | | |
| CHARLOTTE, NC, 28269 | | BURLINGTON, NC, | BURLINGTON, NC, 27215 | | |
| | INS | SPECTION INFORMATION | | | |
| Inspection Date 11/12/2009 | Type Inspection Routine | Certificate Status Re-issued | Inspector 36 - Kirkman | County ALAMANCE | |
| | | VIOLATIONS | | | |
| No violations found | | | | | |
| THE VIELLULE TO MILE | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | iting on Corrected Violations Form v | when the following corrections l | have been made in order to bri | ng your equipment into | |
| omplainace with current codes. | | | T., | | |
| Violations pointed out to: office | | | | | |
| TTY 10 10 10 10 10 10 10 10 10 10 10 10 10 | To make changes to the invoice mailing address please call: 919-733-0372 | | | | |
| THIS IS NOT AN INVOICE | SHADS LANDING An invoice will be mailed to: 5101 PROSPERITY CHURCH ROAD CHARLOTTE, NC, 28269 | | | | |