

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9317-36-2916
State Number 14232

1

	E	QUIPMENT INSPECTED			
State Number: 14232	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: B to 3	
Capacity: 4000	Manuf: THYSSEN	Manuf: THYSSEN KRUPP			
Landings: 4	Installed: 08/22/1991		Rope Size:	Rope Size:	
Volts: 460	Complied: 08/22/1	991	Entrances: 1		
OWNER	OCCUPANT				
KOURY CENTER	KOURY MANANGMENT				
C/O ADVANTIS		3060 S CHURCH ST			
CHAPIL HILL, NC, 27517		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 11/13/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
1 to violations found					
Notify the Elevator Bureau in wromplainace with current codes.	iting on Corrected Violations Form v	when the following corrections l	nave been made in order to bri	ng your equipment into	
/iolations pointed out to: office			Inspector		
-					
TYYO YO X	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE		KOURY CENTER			
	An invoice will be mailed to:	C/O ADVANTIS CHAPIL HILL, NC, 275	17		